

VEHICLE INSPECTION REPORT

C431885

DONBUR CURTAINSIDE

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2016	Colour	BLUE	Brakes	Drum
Year	2016	VIN	SEPPM3DUGL065501	Axle Combi	Tri
Mileage	Not Showing	Body Style	Trailer	Rear Suspension	Air
Fuel Type		MOT Due	Expired	Rear Doors	Barn

FLAT TYRE & TYRE WITH NAIL IN, RAISE & LOWER VALVE, FERRY LASHING RINGS

Tyres

NSF
NSR
OSF
OSR
Spare

Photos





