

VEHICLE INSPECTION REPORT

PJ16YSL

Daf LF 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 17/06/2016

Year 2016

Mileage 1,158,758 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRAEL1500L455284

Body Style Box Van

Service history Yes

MOT Due 28/02/2026

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

Tail Lift Column

COLLECTED AS NON-RUNNER, REAR BUMPER, MIRRORS, ACTUATORS, AIR TANKS & TYRES REQUIRE ATTENTION, WARNING LIGHT ON DASH


Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Cruise control
- Radio/CD
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Other
N/A
N/A



3: Door Mirror Assy nsf
 Scratched (Painted)
 Over 25mm Thru Paint

4: Bumper Front
 Scratched
 Over 100mm Thru Paint



5: Bumper Front Moulding
 Scratched (Painted)
 Over 25mm Thru Paint

6: Other
 N/A
 N/A



7: Bumper Rear
 Rusted
 Holed

8: Qtr Panel osr
 Scratched
 Over 25mm Thru Paint



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint

10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Door osf
Scratched
Over 25mm Thru Paint

12: Door Mirror Assy osf
Broken
Replace



13: Moulding osf Wing
Broken
Replace

14: Seat Base Cover osf
Holed
Over 3mm



15: Seat Base Cover nsf
Holed
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		