

VEHICLE INSPECTION REPORT

FD18VWO

Ford Transit Custom 300 2.0 TDCi 105ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 21/08/2018

Year 2018

Mileage 99,970 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0YXXTTGYJM50168

Body Style Panel Van L1

MOT Due 03/03/2026

CAP Clean £4,575.00

CAP Average £3,950.00

CAP Below £3,075.00

Gearbox MANUAL

Gears 6

SIDE LOADING DOOR, AD BLUE, SPARE WHEEL

Tyres

NSF

NSR

OSF

OSR

Spare


Features

- Front electric windows

Photos



Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 25mm Not Thru Paint



3: Wing nsf
Scratched
UpTo 25mm Not Thru Paint



4: Door nsr
Scratched
UpTo 25mm Not Thru Paint



5: Door nsr
Scratched
UpTo 25mm Thru Paint



6: Lamp osr
Broken
Replace



7: Qtr Panel osr
Dented
With Paint Damage



8: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



9: Door osf
Dented
Over 2 UpTo 10mm



10: Door osf
Chipped
Edge Chip

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Average	Average	Average	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK